
BLACK
RED
MAIN
POWER
POWER SUPPLY
C2
T1
GND 12V GND 12V
GND 12V GND 12V
BLACK
RED
BLACK
RED
TO
FANS
ENABLE
M0
M1
M2
RESET
SLEEP
STEP
DIR
VMOT
GND
B2
B1
A1
A2
FAULT
GND
GECKO 201
POWER GND
24 TO 80VDC
PHASE A
PHASE B
PHASE C
PHASE D
DISABLE
DIR
STEP
COMMON
CURRENT SET
CURRENT SET
14
POWER
2 COM 3 4 COM 5 6 COM 7 COM 8 COM 9 COM
STEPPER
MOTOR
RED
WHITE
BLACK
GREEN
C:\Documents and Settings\Richard\My Documents\3D printer stuff\OJ4233.600.png