

Photos of failure sharp distance sensors




Photo 0. Rear view of the sharp distance sensors.



Photo 1. Power Supply of distance sensors




Photo 2. measurement of the supply voltage in the breadboard




Photo 3. measuring the output voltage of one of the distance sensors without obstruction




Photo 4. measuring the output voltage of another sharp distance sensors without obstruction

Photos 5 to 8. measuring the output voltage of sharp distance sensors with obstruction.




Photo 5.



Photo 6.




Photo 7.



Photo 8.



Photo 9.




Photo 10.



Photo 11.