



Open loop pwm 88%-100%



P KP=1




P KP=5




I KI=1



PD KP=1 KD=1



PI KP=1 KI=1



PID KP=1, KI=1, KD=1

